

Hot-film air mass sensor and control unit HFM5



Criteria:

- dismantled / incomplete
- mechanical damage
- not identifiable

Criterion: dismantled / incomplete



damage to cylinder housing, plug-in sensor, plug connection, strainer element, damage to screws.
only original Bosch plug-in sensor and sensor not missing → not acceptable

Criterion: mechanical damage



damage to cylinder housing, plug-in sensor, plug connection or strainer element
→ not acceptable